




Spindles available in the below finishes (lead time to be applied):



**Raw Iron (RAW)**  
This is raw (unfinished iron, that needs to be painted or powder coated)



**Satin Black (STB)**



**Antique Nickel (AN)**



**Ash Grey (AG)**



**Silver Vein (SP)**



**Satin Clear (SC)**  
This is a clear finish over raw/unfinished iron, variations in surface colour may occur



**Copper Vein (CV)**



**Oil Rubbed Bronze (ORB)**



**Stainless Steel**



**Oil Rubbed Copper (ORC)**



**Vintage Brass (VB)**



**Dorado Gold (GD)**